



December 2013

---

## **C5 Key Fobs**

Every month we are asked to help with C5 Key Fobs that do not work or can't seem to be programmed. Here is the correct way to program a C5 Key Fob, after you have replaced the battery.

### **C5 FOB programming:**

1. Turn ignition on.
2. Turn radio off.
3. Press DIC RESET button.
4. Press OPTIONS on DIC until display is blank.
5. Press and Hold RESET button for 3 seconds.
6. Press OPTIONS button until FOB TRAINING is displayed.
7. Press RESET button to begin programming sequence.
8. Simultaneously press and hold LOCK and UNLOCK buttons on FIRST remote for 13 seconds. Message will appear that 1st FOB programmed.
9. (At this point, on the SECOND FOB, press and hold LOCK and UNLOCK simultaneously for 13 seconds. Message will appear on DIC that 2nd FOB programmed.)
10. Turn ignition off and remove key.
11. Test remotes.

(This will work on both FOBs to open doors, lock doors, open hatch, and IF.....IF you have a #1 and #2 FOB they will set the driver's seat to #1 or #2's preference.). If you happen (as I did) to have two #2's you may use both #2's to unlock/lock/hatch...but NOT seat preference.

Garry

*For more information, or to request answers to your questions, contact Garry;*

Tech@CorvettePerformanceAZ.com